

IPMI Firmware

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X10DRL-I
Release Version	3.80
Release Date	2/14/2019
Previous Version	3.78
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. Patched for CVE-2019-6260 pantsdown. 2. Migrated IPMI Event Log to the URL "redfish/v1/Systems/1/LogServices" in Redfish and renamed the function name from "Event Log" to "System Management Log" in Redfish & Web UI.
New features	N/A
Fixes	1. Fixed problem of degraded & unavailable SEL event appearing after Broadcom 3108 firmware is updated. 2. Allow setting NM power policy by Redfish API. 3. Corrected inability to add AD group name and domain in SMCIPMITool. 4. Allow opening Java IKVM when domain name is used to login to BMC.

Release Notes from Previous Release(s)

3.78 (10/04/2018)

Enhancements

1. Updated IPMI BMC/Onboard LAN MAC address to "00:00:00:00:00:00".
2. Changed FirmwaveInventory to SmcFirmwaveInventory to prevent user confusing with Redfish standard definition.

New features

1. Set the MAC address format to revert to "xx:xx:xx:xx:xx:xx" in order to prevent backward compatibility.
2. Added parameter (SkipCheckingME) for BIOS update in Redfish to skip ME checking.
3. Added support for TaskService feature during BIOS, BMC, and Broadcom storage controller update in Redfish.
4. Added support for Node Manager feature in Redfish.
5. Added new feature for GUID/BoardID in Redfish.
6. Added new feature for event data extension in Redfish.
7. Added support for Redfish TaskMonitor.
8. Implemented Redfish APIs for SSM and SUM.
9. Added support for new Redfish firmware inventory (3108 storage controller) to update firmware.
10. Enabled monitoring of Broadcom 3108 BBU status and logging of it as status change.
11. Added support for saving 3108 storage controller status event.

Fixes

1. Fixed inability to open the 4th iKVM session in Redfish.
2. Fixed the inconsistency in format of an IP address on System page.
3. Fixed incorrect number of spaces between two words.
4. Fixed problem of power consumption history showing minimum power as 0W.
5. Fixed incorrect grammar of some text.
6. Fixed problem of 'M' not following after one period in 'R.P.M'.
7. Fixed incorrect grammar in the alert Window.
8. Fixed issue of Alert email function working properly.
9. Fixed inability to delete Role Group in Active Directory page.
10. Fixed problem of "undefined" message appearing in pop-up window before uploading Broadcom 3108's ROM.
11. Fixed inability to update 3108's firmware over BMC's Web page if Logical device is on the card.
12. Fixed timeout of Invalid Default Active Directory when IPMI 3.73 Redfish test has 1 failed item.
13. Fixed failure of the button to switch to upload in floppy disk after unmounting a file.
14. Fixed failure to change JBOD mode.
15. Fixed problem of the help page of iKVM/HTML5 console not supporting multi-language content.